

Technical Bulletin

Technical Bulletin Index

Bulletin No.	Bulletin Subject	Last Issue
101	Permitted Axial Point Loads	January 17, 2014
102	OSB Moisture Characteristics Relating to Roof decks	July 26, 2007
103	Allowable Header Loads	September 30, 2002
104	Why not apply drywall to panels	February 22, 2003
105	Cyclic (Reversed) Racking Shear Load for High Wind or Seismic Zones	September 25, 2009
105a	NTA Assembly Listings for Insulspan SIP System Seismic Zones A, B, C, D, E & F	May 29, 2017
106	ICC-ES ESR-1295 - Insulspan SIP System	October 7, 2016
107	CCMC Evaluation Report 13016-R - Insulspan SIP System	September 2, 2015
108	One-Hour Fire Resistance Rated Assemblies	September 18, 2015
109	Wall and Roof Cladding Requirements	May 30, 2005
110	Long-Term Thermal Resistance	April 7, 2007
111	Insulspan SIP System ASD and LRFD Shear Wall Design Values	November 15, 2013
112	Roof and Floor Panel Transverse Load Design Charts - US Model Codes	May 27, 2014
113	Wall Panel Design Charts (2x Lumber Splines) - US Model Codes	May 27, 2014
114	Sloped Roof Span and Transverse Design Load Calculation Method	May 27, 2014
115	Wall Panel Design Charts (OSB Splines) - US Model Codes	May 27, 2014

